

FIG. 1.

BEST AVAILABLE COPY

2/5

Test Procedure




Fig 2.


NO₂ Adsorption and Desorption for Conventional NO_x-Trap 120/5:0:1

Fig 3.

BEST AVAILABLE COPY

3/5


Outlet HC for Conventional NO_x-Trap 120/5:0:1

Fig 3A.


NO₂ Adsorption and Desorption for Pt Containing Washcoat

Fig 4.

BEST AVAILABLE COPY

4/5

Outlet HC for Pt Containing Washcoat




Fig 4A.


 NO_2 Adsorption and Desorption for Washcoat minus Pt

Fig 5.

BEST AVAILABLE COPY

5/5

Outlet HC for Washcoat minus Pt




Fig 5A.

BEST AVAILABLE COPY